





WORK STUDY LAB

S.No.	Item Name	Model	Manufacturer	Usage	Picture
1	Roeder Board	32026	Lafayette Inst. Company	To measure hand, arm, finger dexterity, and speed	
2	Peg Board	---	Purdue	To test of fingertip dexterity and gross movement of the hand, fingers and arm	
3	Control Chart	Plastic Balls	--	To draw a control Chart of defectives	
4	Control Chart	Precision	Reshy	To Draw control chart of Variables, Process capability	
5	Time Study	--	--	To estimate time of a bolt washer assembly	